Monitoring after installation and Test Data

Papermaking Industry / Paper packaging line

In the paper packaging line, the degreased chains were used so that they were free of oil or paper dust, but they rusted, causing a problem. They were replaced with TLH Roller Chain, which has not rusted even after 13 months of use






Replaced to TLH Roller chain - After 13 months

Replaced to TLH Roller chain - After 0 month



Replaced to TLH Roller chain - After 4 months

35TLH Appearance check (after washing)



After use, the amount of wear on the pin outside diameter, bushing outside diameter, bushing hole diameter, etc. was 0.005 mm or less, and the TLH layer remained. Thanks to the TLH layer, no rust was observed. In addition, the tensile strength did not decrease and was within the internal standard range.



Tensile Strength Test		Wear Resistance
	35-TLH	35-TLH
JIS Standard Value	7.9(kN)	Elongation: 0.07%
Measured value	10.9(kN)	(without initial antirust oil application)
Cut Point	Inner Plate	
Judgment	Within the Standard Range	

Multistory Parking Industry / Drive Chain

rain. mud. dust. etc.



Hoisting Test

The TLH Roller Chain did not rust after 26,000 hoisting test cycles (outdoors) for 8 months.



Chain Parts After Use (After Washing)

RoHS-Compliant

Corrosion-resistant Roller Chain TLH Series is environmentally friendly and does not contain hazardous substances, such as hexavalent chromium, lead, cadmium, or mercury.

Available with Various Models

TLH treatment is available with various models. Please note that TLH series is unavailable under the following conditions. a) If the chain is in direct contact with food, or there is a possibility that abrasion powder may be mixed into the food.

b) If the chain is used where the TLH coating can be scraped off, such as with an abrasive powder. The coating flakes can fall into the food and cause a problem. Please feel free to contact us when using a chain in cases such as a) and b) above.

In the multi-story car park, the chains were used outdoors, where they were exposed to high humidity with

Outdoor multi-story car park



Drive Chair



Hoisting Chain