
When measuring the length, measure with 6 to 10 links so that the measurement error is minimized.



Figure


ricasaring o links with vernier calipers

Calculate the stretch of chain.

Chain Standard Length X 100 (%)

Measured Length - Standard Length

Standard Length = Chain Pitch x Number of Link



Measuring the chain length Figure