


# Monitoring after installation and Test Data

## Linen Supply Industry / Automatic wet hand towel counting and packing machine

Super Shield Chain was used in a sodium hypochlorite environment, rusting in six months or so, which was a problem. It was replaced with TLH Roller Chain, which did not rust after 54 months of use and is still operating normally even after 66 months of use.



- Sodium hypochlorite environment  
Chlorine gas is generated if a mild acidic solution, with strong bactericidal power, is used.

Super Shield Chain - After 12 months

TLH Roller Chain - After 66 months

## Beverage Industry / Carton filling and transfer line

Stainless steel chains were used for the beverage filling system but they wore and elongated quickly, which was a problem. They were replaced with TLH Roller Chain, which has not elongated or rusted, even after six months of use without maintenance



## Fisheries Industry / Drive chains

Under the clam seawater washing process stainless steel chains wore and elongated quickly, which was a problem. This problem did not recur after the chains were replaced with TLH Roller Chain.

